LMA District Cover Sheet

Spring 2009 Levee Inspection Results

Putah Creek

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)		
* Overall LMA Rating (Fall Only)						
	** Non-receipt of Su	ımmer or Winter Inspe	ection Reports may effec	ct overall annual rating.		
* SPRING INSPECTIONS: Overall maintenance deficiencies are rated		nined for the spring ins ria in the spring and in		ual maintenance		
FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.						
Comments						

Unit Cover Sheet

Spring 2009 Levee Inspection Results

Putah Creek

	Water	way		Bank	Unit Miles			
	Unit No. 01 Putah Cr	o. 01 Putah Creek or North Levee Left 8.99						
	Spring (March - May)	Summer (June - August)	(September - November) Fall		Winter ber - February)			
Unit Maintenance Rating (Fall Only)								
Date of Inspection	4/21/2009 - 4/21/2009							
DWR Inspector	Herman Phillips							
Accompanied By								
Check one:								
project components conditions other that deficiencies identified. During the current with project components maintenance and the following changes in the comment see the com	vinter (or summer) inspection pridentified in the attached Level in the results of our normal maked in the enclosed report. vinter (or summer) inspection pridentified in the attached Level e corrections we have made to a flood project conditions. ction below or on additional ship (Land Side, Water Side, or Conditions)	ee Inspection Report by intenance and the corre period, my staff or I have the Inspection Report by the maintenance deficience eet(s), identify change of	Mile. We have found no chan actions we have made to main a inspected the levee and assorting. In addition to the results sies identified in the report, we of condition by: Start to End Le	ges in flot tenance ociated floof our no have fou	ood project ood ormal and the or GPS			
Comments								
information must also be	3	eet should be signed an	d dated by the LMA Represer th 31 (Winter Inspection). Plea spection Reports , Room LL-30	ntative an	d returned to			

X

Signature of LMA Representative

Date

Levee Inspection Report By Mile - Spring 2009

Putah Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Putah Creek or North Levee	Left	8.99	04/21/2009 04/21/2009	Herman Phillips

LMRL	Levee		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude	Photo	Issue
Line 1	Start	End	Earthen Levee	Vegetation			Control annual grass and weeds on the levee slopes and easements.	Start End		21
2	0.27	0.34	Earthen Levee	Encroachments	LS I	РО	Landscaping	38.520305 ° 38.520000 ° -121.633168 ° -121.634358 °		2
3	0.29	0.29	Earthen Levee	Encroachments	LS I	РО	Buildings	38.520177 ° 38.520177 ° -121.633528 ° -121.633530 °		3
4	0.60	1.16	Earthen Levee	Encroachments	LS I	РО	Agricultural Ditch	38.519632 ° 38.517177 ° -121.639083 ° -121.648702 °		11
5	1.23	1.23	Earthen Levee	Encroachments	LS	М	Equipment	38.516752 ° 38.516752 ° -121.649758 °		4
6	1.55	2.72	Earthen Levee	Encroachments	LS I	РО	Agricultural Ditch	38.515288 ° 38.517438 ° -121.655077 ° -121.676068 °		13
7	5.43	5.49	Earthen Levee	Encroachments	WSI	РО	Crops	38.518120 ° 38.518137 ° -121.723325 ° -121.724433 °		14
8	5.79	5.89	Earthen Levee	Encroachments	WSI	РО	Crops	38.518305 ° 38.518420 ° -121.729815 ° -121.731763 °		15
9	6.76	6.93	Earthen Levee	Encroachments	LS I	РО	Fences	38.517635 ° 38.517675 ° -121.747220 ° -121.750247 °		5
10	7.02	7.09	Earthen Levee	Trim / Thin Trees	WS	С	Trim trees to at least five feet above ground level.	38.517592 ° 38.517672 ° -121.751825 ° -121.753177 °		6
11	7.03	7.07	Earthen Levee	Encroachments	LS I	РО	Fences	38.517565 ° 38.517600 ° -121.751940 ° -121.752697 °		17
12	7.03	7.07	Earthen Levee	Encroachments	LS (со	Landscaping	38.517563 ° 38.517582 ° -121.751980 ° -121.752762 °		8
13	7.67	7.67	Earthen Levee	Trim / Thin Trees	WS	С	Trim trees to at least five feet above ground level.	38.519028 ° 38.519028 ° -121.762870 ° -121.762870 °		18
14	8.44	8.49	Earthen Levee	Trim / Thin Trees	WS	С	Trim trees to at least five feet above ground level.	38.521103 ° 38.521470 ° -121.776192 ° -121.776883 °		19
15	8.50	8.82	Earthen Levee	Encroachments	LS I	PO	Fences	38.521580 ° 38.523932 ° -121.777172 ° -121.782100 °		20

* Location
LS : Land Side
WS : Water Side
CR : Crown

Friday, June 05, 2009 09:58

** Rating

A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected

C : Corrected

Unit Cover Sheet

Spring 2009 Levee Inspection Results

Putah Creek

	Watan	WOW		Bank	Unit Miles
	Waten Unit No. 02 Putah Cre	•		Right	7.30
	Offic No. 02 Futan Cre	tek of South Levee		Rigit	7.30
	Spring (March - May)	Summer (June - August)	(September - November) Fall		Winter ber - February)
Unit Maintenance Rating (Fall Only)					
Date of Inspection	4/22/2009 - 4/22/2009				
DWR Inspector	Herman Phillips				
Accompanied By					
Check one:					
project components conditions other that deficiencies identified. During the current with project components maintenance and the following changes in (In the comment sec	vinter (or summer) inspection p identified in the attached Leve in the results of our normal mai ed in the enclosed report. vinter (or summer) inspection p identified in the attached Leve e corrections we have made to in flood project conditions. ction below or on additional she in (Land Side, Water Side, or Co	e Inspection Report by intenance and the correction, my staff or I have a Inspection Report by maintenance deficience eet(s), identify change of	Mile. We have found no chan actions we have made to main a inspected the levee and assorting. In addition to the results sies identified in the report, we of condition by: Start to End Le	ges in flo tenance ociated flo of our no have fou	ood project ood ormal ind the or GPS
Comments					
information must also be s	3	eet should be signed an	d dated by the LMA Represer th 31 (Winter Inspection). Plea spection Reports , Room LL-30	itative an	d returned to

X

Signature of LMA Representative

Date

Levee Inspection Report By Mile - Spring 2009

Putah Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Putah Creek or South Levee	Right	7.30	04/22/2009 04/22/2009	Herman Phillips

LMR Line	Levee	Mile End	Category	Item	Rating ** Location *	Action/Comment	GPS Latitude/Longitude Start End	Issue
1	0.00	0.28	Earthen Levee	Encroachments	WS PO	Agricultural Ditch	38.504930 ° 38.508830 ° -121.663150 ° -121.663280 °	24
2	0.17	0.32	Earthen Levee	Encroachments	LS PO	Agricultural Ditch	38.507113 ° 38.509088 ° -121.662687 ° -121.663443 °	3
3	2.10	2.13	Earthen Levee	Animal Control	LS M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.515348 ° 38.515398 ° -121.694042 ° -121.694590 °	22
4	2.10	2.13	Earthen Levee	Animal Control	WS M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.515350 ° 38.515385 ° -121.694110 ° -121.694558 °	23
5	5.89	5.95	Earthen Levee	Animal Control	LS M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.516072 ° 38.516082 ° -121.760790 ° -121.761850 °	5
6	5.93	5.95	Earthen Levee	Encroachments	LS PO	Agricultural Ditch	38.516680 ° 38.516660 ° -121.764310 ° -121.765130 °	25
7	6.59	6.65	Earthen Levee	Encroachments	WS PO	Crops	38.518088 ° 38.518353 ° -121.772947 ° -121.773935 °	6
8	6.62	6.65	Earthen Levee	Trim / Thin Trees	WS C	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.518210 ° 38.518353 ° -121.773460 ° -121.773932 °	7
9	6.65	6.65	Earthen Levee	Encroachments	LS C	Prunings	38.518352 ° 38.518352 ° -121.773945 ° -121.773945 °	8
10	6.69	6.71	Earthen Levee	Trim / Thin Trees	LS C	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.518583 ° 38.518668 ° -121.774612 ° -121.774795 °	21
11	6.76	6.80	Earthen Levee	Trim / Thin Trees	LS C	Trim trees to at least five feet above ground level.	38.519128 ° 38.519462 ° -121.775703 ° -121.776318 °	20
12	6.81	6.81	Earthen Levee	Encroachments	LS C	Buildings	38.519668 ° 38.519668 ° -121.776280 ° -121.776280 °	10
13	6.97	6.97	Earthen Levee	Encroachments	WS C	Tree or limb	38.520833 ° 38.520833 ° -121.778678 ° -121.778678 °	18
14	7.13	7.13	Earthen Levee	Trim / Thin Trees	WS C	Trim trees to at least five feet above ground level.	38.522077 ° 38.522077 ° -121.781128 ° -121.781128 °	16
15	7.14	7.14	Earthen Levee	Encroachments	ws c	Tree or limb	38.522140 ° 38.522140 ° -121.781263 ° -121.781263 °	17
16	7.23	7.23	Earthen Levee	Encroachments	WS C	Tree or limb	38.522653 ° 38.522647 ° -121.782615 ° -121.782748 °	14
17	7.24	7.30	Earthen Levee	Encroachments	WS PO	Crops	38.522752 ° 38.522685 ° -121.782912 ° -121.784757 °	13

* Location LS : Land Side WS : Water Side CR : Crown

** Rating

A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected

C : Corrected